

Republic of the Philippines Department of Environment and Natural Resources

NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY

Date: 30 August 2016

Reference: SBMA Seaport Dept. eMail

(HD 118/16)

Subject: NAVPHIL.INFORMATION

No. of Pages: 1

MESSAGE

NAVPHIL 060/16 - LUZON, W. COAST, SUBIC BAY - BUOY

CHIQUITA ISLAND BUOY (NAVIGATIONAL BUOY #2) AT POSITION 14° 45' 50"N., 120° 13' 19"E. IN THE FAIRWAY OF SUBIC BAY PORT HAS BEEN REPORTED DRIFTED LAST 20 AUGUST 2016. SAID BUOY WAS RECOVERED AND TEMPORARILY SECURED IN ONE OF SUBIC BAY METROPOLITAN AUTHORITY'S (SBMA) PORT FACILITIES.

THE FOLLOWING BUOYS WERE ALSO REPORTED TO BE OUT OF THEIR DESIGNATED LOCATIONS:

BUOY No.	NAME	COORDINATES
1	TWENTY FOUR FOOT SHOAL	14° 45' 04.21"N., 120° 13' 28.39"E.
4	MACMANY POINT	14° 46' 29.72"N., 120° 12' 15.47"E.
7	MAIN TRAFFIC LANE EAST	14° 47' 17.12"N., 120° 13' 57.12"E.
10	MAIN TRAFFIC LANE CENTER	14° 48' 42.05"N., 120° 15' 00.14"E.
11	MAYANGA ISLAND	14° 49' 36.61"N., 120° 14' 04.02"E.
14	REPAIR YARD TRAFFIC LANE WEST	14° 50' 27.17"N., 120° 13' 09.87"E.
15	REPAIR YARD TRAFFIC LANE EAST	14° 50' 58.77"N., 120° 13' 20.75"E.
16	REPAIR YARD TRAFFIC LANE WEST	14° 50' 58.77"N., 120° 13' 03.81"E.
17	REPAIR YARD TRAFFIC LANE WEST	14° 51' 53.80"N., 120° 13' 03.44"E.
21	OFF NABASAN WHARF	14° 46' 33.19"N., 120° 15' 15.15"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES.

Commodore JACINTO M CABLAYAN

Please advise by phone/fax if any part of this message is not received

