

Republic of the Philippines Department of Environment and Natural Resources

National Mapping and Resource Information Authority Hydrography Branch

421 Barraca Street, San Nicolas Manila, Philippines

Date: 14 April 2016

Reference: PCG NTM 038-2016

(HD 047/16)

Subject : NAVPHIL.INFORMATION

No. of Pages: 1

MESSAGE

NAVPHIL 026/16 - CEBU-MACTAN CHANNEL - REPAIR AND REHABILITATION

REPAIR AND REHABILITATION OF 1ST CEBU-MACTAN BRIDGE STARTED LAST 02 APRIL 2016 LOCATED AT THE NORTH ENTRANCE OF CEBU-MACTAN CHANNEL OR AT THIS POSITION.

10° 19.12' N. 123° 57.35' E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA TO BE VIGILANT AND EXTRA CAUTIONS FROM POSSIBLE FALLING DEBRIS/OBJECT WHILE TRANSTING UNDER THE BRIDGE ARE ADVISED TO TAKE NECESSARY PRECAUTIONARY MEASURES.

for Commodore JACINTO M CABLAYAN

Please advise by phone/fax if any part of this message is not received

