

Republic of the Philippines Department of Environment and Natural Resources

NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY

Date: 27 June 2017

Reference: SBMA Seaport Dept. eMail

(HD 115/17)

Subject: NAVPHIL.INFORMATION

No. of Pages: 1

MESSAGE

NAVPHIL 075/17 - LUZON, W. COAST, SUBIC BAY - MISSING BUOY

AGUSUHIN POINT BUOY, AT POSITION 14° 48' 19"N., 120° 13' 02"E., HAS BEEN REPORTED SUNK AT THE BOTTOM OF THE SEA LAST 14 JUNE 2017.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES.

Commodore JACINTO M CABLAYAN

Director, Hydrography Branch

Please advise by phone/fax if any part of this message is not received