

Republic of the Philippines

Department of Environment and Natural Resources

NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY

www.namria.gov.ph

Date: 26 June 2019

Reference: Rappler.com News

(HD 169/19)

Subject: NAVPHIL.INFORMATION

No. of Pages: 1

**MESSAGE** 

NAVPHIL 077/19 - CEBU, E. COAST, CEBU STRAIT - CAPSIZED VESSEL

THE CARGO VESSEL MV EVA MARY GRACE, LOADED WITH BAGS OF CEMENT, REPORTEDLY CAPSIZED ON 25 JUNE 2019 AT SEDC PORT, SAN FERNANDO, CEBU AT APPROXIMATE POSITION:

10° 09' 16"N., 123° 42' 27"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Commodore JACINTO M CABLAYAN

Director, Hydrography Branch

Please advise by phone/fax if any part of this message is not received



